

- Sent to CERN on 18 July 2005.
 - Firmware 006/clock hardware fix NOT done.
 - Final QA not done.
 - Designated "superbright" for TX testing purposes.
 - Tx plugins replaced on 18 May 2009:
 - ◆ Old: T2225, T2226, T2227, T2229
 - ◆ New: T2296, T5026, T5065, T5069
 - Tx0 plugin replaced on 24 April 2012: Old T2296, New ST407
 - Rx plugins changed in July 2013 (0-7): SR413 SR414 SR415 SR416 SR417 SR418 SR419 SR420
-
- Wont configure, and BOC light no lit on matching ROD - removed for shipment to Cambridge September 2013

-- JohnHill - 21-Aug-2013

This topic: Main > AtlasSctBoc_077

Topic revision: r7 - 2013-11-08 - DaveRobinson



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback