

- Received at CERN ~June 2003
- Used at Liverpool for Endcap C assembly
- Installed in USA15 on 20 April 2006 (Y.22-11.A2.U28)
- Went faulty on 25 October 2006: both +12V and -12V report "low voltage"
- Given to Loan Pool to send off for repair on 27 October 2006
- Repaired and returned to us on 25 July 2007.
- Installed in USA15 (Y.25-14.A2.U08) on 27 July 2007.
- Weiner modification made by Bartek on 17 February 2009 - brief testing done.

-- JohnHill - 18 Feb 2009

This topic: Main > AtlasSiliconPS_08

Topic revision: r4 - 2009-02-18 - JohnHill



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
Ideas, requests, problems regarding TWiki? Send feedback