

Table of Contents

Shutdown activities.....	1
Sub detectors.....	1
LHCb Shutdown activities.....	2

Shutdown activities

This page refers to activity for the Jan-Feb 2010 shutdown.

For access requests and overview refer to this page on the online twiki [↗](#)

Sub detectors

Timetable

September	
<<Mo	Tu We Th Fr >>
16	17 18 19 20
07:00	07:00
08:00	08:00
09:00	09:00
10:00	10:00
11:00	11:00
12:00	12:00
13:00	13:00
14:00	14:00
15:00	15:00
16:00	16:00
17:00	17:00
18:00	18:00
19:00	19:00
20:00	20:00

- 29 Jan 2010 - 29 Jan 2010 - 08:00-23:00 Pump down of beam pipe
- 01 Feb 2010 - 01 Feb 2010 - 06:00-15:00 No access - maintenance CV - no ventilation.
- 02 Feb 2010 - 02 Feb 2010 - 06:00-17:00 Limited access into the cavern! Alarm transmission test.
- 19 Jan 2010 - 22 Jan 2010 - 09:00-21:00 VELO: exchange of filters in cooling system
- 20 Jan 2010 - 25 Jan 2010 - 08:00-19:00 RICH 2: Exchange of HPDs
- 20 Jan 2010 - 22 Jan 2010 - 08:00-18:00 Muon: Exchange chamber on M2 side C front
- 21 Jan 2010 - 21 Jan 2010 - 14:00-18:00 Survey: Muon station
- 25 Jan 2010 - 25 Jan 2010 - 14:00-18:00 Survey: RICH 2
- 26 Jan 2010 - 26 Jan 2010 - 14:00-18:00 Survey: RICH 2

LHCb Shutdown activities

Sub detector	Task	Responsible	start_DATE	end_DATE	Access Request	Work statement
	Templates		2010-01-26		Template ↗	TEMPLATE ↗
Beam Pipe	Venting	G. Schneider	2010-01-04	2010-01-07	UX85B-S-2010-001	n/a
Infrastructure	Intervention sur 3 Turbines Muon	L. Roy	2010-01-06	2010-02-12	UX85B-S-2010-002	IX0001-2010 ↗
Tracker Turicensis	Work on service boxes	J.v Tilburg	2010-01-11	2010-01-12	UX85B-S-2010-003	n/a
Infrastructure	Installation of RICH 1 crane control	B. Corajod	2010-01-07	2010-01-08	UX85B-S-2010-004	IX0002-2010 ↗
Infrastructure	Installation of distance pieces between RICH 1 rail and magnet	C. Fournier, G. Decreuse	2010-01-08	2010-01-08	UX85B-S-2010-004	IX0003-2010 ↗
Infrastructure	Replace Teflon washer for RICH 1 crane	C. Fournier, G. Decreuse	2010-01-08	2010-01-08	UX85B-S-2010-004	IX0004-2010 ↗
RICH 2	Look for Gas Leak	C. Frei, O. Ullaland	2010-01-11	2010-01-18	UX85B-S-2010-005	RD0001-2010 ↗
VELO	VELO cooling intervention	E. Jans	2010-01-19	2010-01-22	UX85B-S-2010-006	TV0001-2010 ↗
Inner Tracker	Daily cooling check	F. Blanc	2010-01-12	2010-01-29	UX85B-S-2010-007	n/a
Inner Tracker	Fix read-out	F. Blanc	2010-01-12	2010-01-29	UX85B-S-2010-008	n/a
RICH 2	Optical fiber power measurement	K. Wyllie	2010-01-12	2010-01-12	UX85B-S-2010-009	n/a
Outer Tracker	Open OT3 for FE exchange	A. Pellegrino	2010-01-13	2010-01-14	UX85B-S-2010-010	OT0001-2010
Outer Tracker	Work on OT1-OT3	A. Pellegrino	2010-01-15	2010-01-29	UX85B-S-2010-011	OT0001-2010
Infrastructure	General work	R. Lindner	2010-01-12	2010-02-12	UX85B-S-2010-012	n/a
RICH 2	HPD replacment	D. Piedigrossi	2010-01-20	2010-01-25	UX85B-S-2010-014	RD0002-2010 ↗
Muon	Change of a MWPC	B. Schmidt	2010-01-20	2010-01-22	UX85B-S-2010-015	UX0001-2010 ↗
Outreach	3d movies, Films + interviews	Bolek PIETRZYK	2010-01-21	2010-02-01	UX85B-S-2010-016	OutreachWork
ECAL	TVB replacment	M.N Minard	2010-01-26	2010-01-26	UX85B-S-2010-017	
Beam Pipe	Pumping down of Beam Pipe	G. Schneider	2010-01-29	2010-01-29	UX85B-S-2010-001	

LHCbActivitiesShutdown2010 < LHCb < TWiki

Outer Tracker	Irradiation tests	A.Pellegrino	2010-01-27	2010-01-29	UX85B-S-2010-018	
Calorimeter	Repair SPECS Mezzanine of CALORIMETER HV System	P. Perret	2010-02-02	2010-02-02	UX85B-S-2010-019	
Calorimeter	Replacement of calorimeter front-end boards	Frédéric Machefert	2010-02-02	2010-02-03	UX85B-S-2010-020	
Safety	Fire Brigade Visit of Underground Facilities	Eric Thomas	2010-01-28	2010-01-28	UX85B-S-2010-021	
Safety	Fire Brigade Visit of Underground Facilities	Eric Thomas	2010-02-10	2010-02-10	UX85B-S-2010-022	
RICH 2	Gas Enclosure Tightness: improvements and checks	Christophe Frei	2010-02-01	2010-02-08	UX85B-S-2010-023	RD-0003-2010
Outer Tracker	Re-commission OT	Antonio Pellegrino	2010-02-02	2010-02-12	UX85B-S-2010-024	RD-0004-2010
Outer Tracker	Work on OT gas system	Sebastian Bachmann	2010-02-02	2010-02-05	UX85B-S-2010-025	
VELO	Repair on VELO C-side cooling system	Eddy Jans	2010-02-04	2010-02-05	UX85B-S-2010-026	
HCAL	Source calibration of HCAL	Yury Guz	2010-02-05	2010-02-05	UX85B-S-2010-027	
Inner Tracker	Daily access to check cooling system + measure height of IT stations	Fred Blanc	2010-02-02	2010-02-12	UX85B-S-2010-028	
Calorimeter	Control of cable connections	Frédéric Machefert	2010-02-04	2010-02-04	UX85B-S-2010-029	
Calorimeter	Test of the trigger cabling ECAL / Preshower board	Regis Lefevre	2010-02-04	2010-02-04	UX85B-S-2010-030	
Outer Tracker	Installation of OT protection	Antonio Pellegrino	2010-02-08	2010-02-12	UX85B-S-2010-031	RD-0005-2010
Infrastructure	Checks of RP measurement devices in presence of magnetic field	Gloria Corti	2010-02-08	2010-02-08	UX85B-S-2010-032	RD-0006-2010
ECAL	Replacement of a front-end board	Frédéric Machefert	2010-02-08	2010-02-08	UX85B-S-2010-033	
RICH 2	RICH 1/2 Gas system restart	Christophe Frei	2010-02-08	2010-02-12	UX85B-S-2010-034	RD-0007-2010
Infrastructure	OT access side A	C. Fournier	2010-02-09	2010-02-09	UX85B-S-2010-004	IX0005-2010 ↗
Infrastructure		C. Fournier	2010-02-01	2010-02-11	UX85B-S-2010-004	RD0008-2010 ↗

LHCbActivitiesShutdown2010 < LHCb < TWiki

	RICH 2 tower modification					
ECAL	Specs problem fixation	A. Konoplyannikov	2010-02-09	2010-02-09	UX85B-S-2010-035	RD-0009-2010
SPD	Check SPD regulators board	D. Esperante	2010-02-12	2010-02-12	UX85B-S-2010-036	
VELO	Fix loose cable	K. Hennessy	2010-02-12	2010-02-12	UX85B-S-2010-037	
SPD	Replace problematic regulators board	P. Perret / D. Esperante	2010-02-15	2010-02-17	UX85B-S-2010-038	
Infrastructure	General work	R. Lindner	2010-02-15	2010-02-18	UX85B-S-2010-039	
Calorimeter	FEE change on HCAL	P. Perret	2010-02-19	2010-02-19	UX85B-S-2010-040	
Infrastructure	Area cleaning	G. Corti	2010-02-18	2010-02-18	UX85B-S-2010-041	
Calorimeter	FEE change on HCAL	F. Machefert	2010-02-22	2010-02-22	UX85B-S-2010-042	
Calorimeter	TVB replacement	P. Perret	2010-02-23	2010-02-23	UX85B-S-2010-043	

-- RolfLindner - 05-Jan-2010

This topic: LHCb > LHCbActivitiesShutdown2010

Topic revision: r99 - 2010-09-02 - GloriaCorti



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback