

- Sent to CERN on 27 July 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 22 March 2007.

All four TX plugins removed for replacements for faulty plugins in USA15 (24/4/08):

- ST295 from position 1 (to BOC096)
- ST296 from position 2 (to BOC096)
- ST293 from position 0 (to BOC041)

Noticed that 2 caps were missing in September 2013: C149 and C33

- Replaced at CERN by Sergei Katunin

06.05.2019 - broken vme interface - extracted from crate 5 slot 5 for shipment to Cambridge

-- JohnHill - 30 Sep 2008

This topic: Main > AtlasSctBoc_041

Topic revision: r5 - 2019-05-06 - DaveRobinson



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback