

- Sent to CERN on 27 July 2005.
  - Firmware 006/clock hardware fix NOT done.
  - Final QA not yet done.
  - Installed in SR1 Test Setup
  - Removed from SR1 on 6 June 2006 by John Hill.
- 
- Firmware 006/clock mod now done as at 26/9/2008
  - Final QA done.
  - Installed in USA15 on 13 November 2008.
  - Tx plugins replaced on 29 July 2009:
    - ◆ Old: ST242, ST243, ST253, ST245
    - ◆ New: T5326, T5328, T5329, T5330
  - Tx2 failed. Replaced on 26 August: Old T5329, New T3190
  - Tx3 replaced on 23 November 2010. Old T5330, New ST096
  - All 4 Tx plugins replaced on 4 July 2011:
    - ◆ Old: T5326, T5328, T3190, ST096
    - ◆ New: T6207, T6199, T6191, T6189

-- JohnHill - 06-Jul-2011

---

This topic: Main > AtlasSctBoc\_044

Topic revision: r9 - 2011-07-06 - JohnHill



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.  
or Ideas, requests, problems regarding TWiki? use [Discourse](#) or [Send feedback](#)