

- Sent to Oxford for Barrel Assembly on 25 February 2005.
- Returned to Cambridge on 2 September 2005.
- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 19 May 2006.
- Installed in USA15 on 5 June 2006.
- Tx plugins replaced on 27 July 2009:
  - ◆ Old: ST163, ST083, ST165, ST194
  - ◆ New: T5585, T5586, T5587, T5589
- Tests showed BPM errors on Tx1,Tx2,Tx3 caused by fault (addressing??) on Tx0 (T5549). Replaced by T5345 on 31 July 2009 - OK now.
- Hence Tx plugins now (31 July 2009): T5345, T5550, T5551, T5552
- Tx0 relaced on 20 October 2010. Old T5345, New T2195
- Tx2 replaced on 5 November 2010. Old T5551, New ST160
- Tx1 and Tx3 replaced on 1 March 2011. Old T5550 and T5552. New T6146 and T6145
- All 4 Tx plugins replaced on 28 February 2012:
  - ◆ Old: T2195, T6146, ST160, T6145
  - ◆ New: T6814, T6817, T6816, T6815
- Rx plugins changed in July 2013 (0-7): SR327 SR323 SR324 SR325?? SR326 SR325?? SR377 SR332

-- JohnHill - 21-Aug-2013

---

This topic: Main > AtlasSctBoc\_055

Topic revision: r9 - 2013-08-21 - JohnHill



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.  
or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback