

- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 28 April 2006.
- Installed in USA15 on 28 April 2006.
- Tx plugins replaced on 28 July 2009:
  - ◆ Old: ST324, ST325, ST327, ST328
  - ◆ New: T5379, T5381, T5290, T5291
- Tests showed all channels very low power on Tx1 (T5381). Replaced on 30 July 2009 by T5332. new Tx good.
- Hence Tx plugins now (30 July 2009): T5379, T5332, T5290, T5291
- Tx0 replaced on 9 August 2010. Old: T5379, New: T3134
- Tx3 replaced on 18 November 2010. Old T5291, New ST088
- All 4 Tx plugins replaced on 26 August 2011:
  - Old
    - T3134, T5332, T5290, ST088
  - New
    - T6335, T6336, T6337, T6338

-- JohnHill - 30-Aug-2011

---

This topic: Main > AtlasSctBoc\_081

Topic revision: r5 - 2011-08-30 - JohnHill



Copyright &© 2008-2020 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.  
Ideas, requests, problems regarding TWiki? Send feedback