

- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 27 April 2006.
- Installed in USA15 on 28 April 2006.
- Removed from USA15 on 13 November 2008
- Installed in USA15 on 29 March 2011 - replaced faulty board C123
- Tx Plugins are: T5759, T5761, T5762, T5583
- All 4 Tx plugins replaced on 15 August 2011.
 - ◆ Old: T5759, T5761, T5762, T5583
 - ◆ New: T6285, T6286, T6287, T6288
- Rx plugins changed in July 2013 (0-7): x x SR805 SR806 SR807 SR808 SR809 SR810

-- JohnHill - 23-Aug-2013

This topic: Main > AtlasSctBoc_101

Topic revision: r5 - 2013-08-23 - JohnHill



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback