

- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 27 April 2006.
- Installed in USA15 on 27 April 2006.

- Suspect dead TX plugin, so removed from USA15:Y.24-14.A2.U28.07R to B186 on 05/08/2008 (DR)

- Tx1 replaced 26/9/2008 (was ST366, now ST030)

- Installed in USA15 on 13 November 2008.
- Tx plugins replaced on 28 July 2009:
 - ◆ Old: ST365, ST030, ST367, ST368
 - ◆ New: T5133, T5132, T5131, T5130
- Tx3 failed: T5130 replaced by T3117 on 19 July 2010
- Tx1 replaced on 17 October 2010. Old T5132, new T2200
- Tx2 replaced on 6 November 2010. Old T5131, new ST402
- Tx0 replaced on 2 March 2011. Old T5133, New T6083
- Tx3 replaced on 1 August 2011. Old T3117, New ST521
- All 4 Tx plugins replaced on 28 February 2012:
 - ◆ Old: T6083, T2200, ST402, ST251

-- JohnHill - 06-Mar-2012

This topic: [Main > AtlasSctBoc_103](#)

Topic revision: [r11 - 2012-03-06 - JohnHill](#)



Copyright &© 2008-2020 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? [Send feedback](#)