

- Sent to CERN on 1 March 2006.
- Firmware 006/clock hardware fix done.
- Final QA done on 18 May 2006.
- Installed in USA15 on 5 June 2006.
- Tx plugins replaced on 19 May 2009:
 - ◆ Old: ST382, ST383, ST384, ST385
 - ◆ New: T5067, T5076, T5077, T5079
- Later operation showed what appears to be an addressing fault on Tx2 BPM (T5077). Replaced on 30 July 2009 by T5384.
- Hence Tx plugins now (30 July 2009): T5067, T5076, T5384, T5079
- Tx2 replaced on 1 March 2011. Old T5384, New T6107
- Tx1 replaced on 17 March 2011. Old T5076, New T6130
- Tx0 replaced on 6 September 2011. Old T5067, New T6097
- All 4 Tx plugins replaced on 25 November 2011:
 - ◆ Old: T6097, T6130, T6107, T5079
 - ◆ New: T6634, T6635, T6636, T6637
- Rx plugins changed in July 2013 (0-7): SR851 SR852 SR853 SR854 SR855 SR856 SR857 SR858

-- JohnHill - 21-Aug-2013

This topic: Main > AtlasSctBoc_107

Topic revision: r8 - 2013-08-21 - JohnHill



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback