

- Sent to CERN on 8 May 2006.
- Firmware 006/clock hardware fix done.
- Final QA done on 17 May 2006.
- Installed in USA15 on 5 June 2006.
- Removed from USA15 Sep/Oct 2008 - reason???
- Installed in USA15 on 13 November 2008.
- Tx plugins replaced on 28 July 2009:
 - ◆ Old: ST537, ST538, ST539, ST540
 - ◆ New: T5137, T5136, T5135, T5134
- Tx3 replaced on 17 October 2010. Old T5134, New T2209
- Tx2 replaced on 20 October 2010. Old T5135, New T2221
- Tx1 replaced on 23 November 2010. Old T5136, new ST208
- Tx0 replaced on 2 March 2011. Old T5137, New T6135
- All 4 Tx plugins replaced on 28 February 2012:
 - ◆ Old: T6135, ST208, T2221, T2209
 - ◆ New: T6601, T6611, T6612, T6613

-- JohnHill - 06-Mar-2012

This topic: Main > AtlasSctBoc_129

Topic revision: r9 - 2012-03-06 - unknown



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback