

- Sent to CERN in June 2013
- Broken insertion lever (bottom lever), repaired by Dave

-- JohnHill - 11-Jul-2013

This topic: Main > AtlasSctBoc_218

Topic revision: r2 - 2013-11-08 - DaveRobinson



Copyright &© 2008-2020 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

or Ideas, requests, problems regarding TWiki? use [Discourse](#) or [Send feedback](#)