

-- AndreasKorn - 16 Jan 2007

- arrived at CERN 12 Jan 2007
- passed burnttest in USA15, but out of synch MDSP led
- checked jumpers, still out of synch with TIM
- works in a different crate, but slot works with a different ROD too
- returned to CERN from Repair 17 Aug 2007
- passed second burnttest in USA15, but still out of synch MDSP led

This topic: Main > AtlasSiliconROD_242

Topic revision: r5 - 2007-09-28 - AndreasKorn



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback