

-- AndreasKorn - 15 Jan 2007

- arrived at CERN 25 Sep 2006, not fully tested yet
 - command line 7 is dead, checked in Pixellab with LoopBackCard
 - Visual inspection shows a suspicious solder pad on driver chip U48 pin37 (e.g. the input driving line 7).
 - returned to CERN from Repair 17 Aug 2007
-

This topic: Main > AtlasSiliconROD_307

Topic revision: r3 - 2007-08-22 - AndreasKorn



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback