

-- AndreasKorn - 09 Feb 2006

- arrived at CERN 2 Feb 2006, tested with ROD CLK 2 Feb 2006
  - installed in SR1 5 Apr 2006
  - installed in USA15
  - occurrence of dead MDSP possibly bad configuration, fixed by reset
  - modified for SCT by JJ November 2019
- 

This topic: Main > AtlasSiliconRod\_207

Topic revision: r4 - 2019-12-10 - DaveRobinson



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback