

-- AndreasKorn - 09 Feb 2006

- arrived at CERN 2 Feb 2006, tested with ROD CLK 3 Feb 2006
- installed in SR1 5 Apr 2006
- problems with Slink Xoff, after power cycle xoff state is always on, needs SLink reset
- moved to pixellab for John to debug 6 Nov 2006
- moved to USA15

This topic: Main > AtlasSiliconRod_212

Topic revision: r4 - 2007-11-19 - AndreasKorn



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors. Ideas, requests, problems regarding TWiki? Send feedback