



Energy flow distribution in the eta/phi plan using 2011 splash events from beam 1, in the second layer of the endcap electromagnetic calorimeter. The eight-fold structure of the end-cap toroid is clearly visible. The change of granularity of the calorimeter at eta=2.5 explains the structure of the plot. This distribution illustrates the status of the detector after the FEB replacement during the winter 2010-2011 shutdown.