

TestBeamPreparation < DREAM < TWiki

1. DWC calibration
2. check DAQ
3. check sampler (histogram production)
4. check adc gates and tdc start/stop signals

-- MicheleCascella - 2014-11-27

This topic: DREAM > TestBeamPreparation

Topic revision: r1 - 2014-11-27 - MicheleCascella



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback