

-- Main.pyduval - 27 Jul 2007

When logged on a control room station (LB015) for us:

- Start Exceed on the station
- Use Putty to log on tmudaq01 on piyvduval account
- Redirect the X display on the station >>export DISPLAY=LB015W:0.0<< or use the alias >>disp<<
- type the command >>startPA 3.6 & << the PVSS administratot tool window should appear.

Once PVSS is started select the L0MUON_TRIG project and start it. Then select the toolBox.pnl to access the tolls to manage the CCPC remotely.

This topic: LHCb > L0MuonHowToLaunchToolBoxUtility

Topic revision: r3 - 2007-10-15 - PierreYvesDuval



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback