

Table of Contents

SW-DAQ-01 port assignment for Farm racks.....	1
Linecard 0.....	1
Linecard 13.....	1

SW-DAQ-01 port assignment for Farm racks

Linecard 0

Ports	To rack
7-9	D1E08
22-24	D1E04
31-33	D1E06
43-45	D1E09
54-59	D1E10

Linecard 13

Ports	To rack
7-9	D1E08
22-24	D1E04
31-33	D1E06
43-45	D1E09

This topic: LHCb > SwDaq01

Topic revision: r2 - 2007-09-14 - unknown



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback