

- Sent to CERN on 21 January 2005.
- Returned to Cambridge on 8 August 2005.
- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 28 April 2006.
- Installed in USA15 on 28 April 2006.
- Tx plugins replaced on 29 July 2009:
 - ◆ Old: ST102, ST109, ST113, ST115
 - ◆ New: T5044, T5045, T5331, T5333
- Tx plugins failed: Tx0: T5044 replaced by T3281; Tx2: T5331 replaced by T3179; on 27 July 2010
- Tx1 replaced on 23 November 2010. Old T5045, New ST401
- Tx3 replaced on 1 March 2011. Old T5333, New T6098
- All 4 Tx plugins replaced on 26 August 2011:
 - ◆ Old: T3281, ST401, T3179, T6098
 - ◆ New: T6294, T6295, T6296, T6297

-- JohnHill - 30-Aug-2011

This topic: Main > AtlasSctBoc_050

Topic revision: r6 - 2011-08-30 - JohnHill



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback