

- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 28 April 2006.
- Installed in USA15 on 28 April 2006.
- Tx plugins replaced on 27 July 2009:
  - ◆ Old: ST259, ST260, ST261, ST262
  - ◆ New: T5569, T5570, T5571, T5572
- Tx0 failed: T5569 replaced by T3105 on 20 July 2010
- Tx3 replaced. Old T5572. New: T2189 replaced on 6 October 2010
- Tx1 replaced on 29 July 2011. Old T5570, new ST468
- All 4 Tx plugins replaced on 28 February 2012:
  - ◆ Old: T3105, ST468, T5571, T2189
  - ◆ New: T6794, T6795, T6796, T6797
- Tx1 replaced on 14 August 2012: Old T6795, New T6826
- Rx plugins changed in July 2013 (0-7): SR650?? SR651 SR652 SR653 SR654 SR655 SR656 SR657

-- JohnHill - 21-Aug-2013

---

This topic: Main > AtlasSctBoc\_059

Topic revision: r8 - 2013-08-21 - JohnHill



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors. Ideas, requests, problems regarding TWiki? Send feedback