

- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 26 April 2006.
- Installed in USA15 on 27 April 2006.
- Tx plugins replaced on 29 July 2009:
  - ◆ Old: ST263, ST264, ST265, ST266
  - ◆ New: T5179, T5180, T5182, T5183
- Tx0 replaced on 28 September 2010. Old: T5179, New T3224
- Tx3 replaced on 20 October 2010. Old T5183, New ST457
- Tx1 replaced on 27 October 2010. Old T5180, New ST396
- Tx2 replaced on 3 December 2010. Old T5182, new ST367
- Tx0, Tx1, Tx2, Tx3 replaced on 1 March 2011. Old T3224, ST396, ST367, ST457. New T6084, T6155, T6148, T6156
- All 4 Tx plugins replaced on 28 February 2012:
  - ◆ Old: T6084, T6155, T6148, T6156
  - ◆ New: T6716, T6717, T6718, T6719

-- JohnHill - 06-Mar-2012

---

This topic: Main > AtlasSctBoc\_061

Topic revision: r10 - 2012-03-06 - JohnHill



Copyright &© 2008-2020 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback