

- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 7 April 2006.
- Installed in USA15 on 15 May 2006.
- Tx plugins replaced on 27 July 2009:
 - ◆ Old: ST295, ST104, ST296, ST106
 - ◆ New: T5560, T5561, T5562, T5563
- Tx1 replaced on 30 August 2010. Old T5561, New T3174
- Tx2 replaced on 1 March 2011. Old T5562, New T6114
- Tx0 replaced on 13 July 2011. Old T5560, New T6116
- All 4 Tx plugins replaced on 28 February 2012:
 - ◆ Old: T6116, T3174, T6114, T5563
 - ◆ New: T6786, T6787, T6788, T6789
- Rx plugins changed in July 2013 (0-7): SR122 SR123 SR124 SR128 SR129 SR130 SR132 SR134

-- JohnHill - 21-Aug-2013

This topic: Main > AtlasSctBoc_096

Topic revision: r7 - 2013-08-21 - JohnHill



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback