

- Sent to CERN on 17 November 2005.
- Firmware 006/clock hardware fix done.
- Final QA done on 27 April 2006.
- Installed in USA15 on 27 April 2006.
- Tx plugins replaced on 29 July 2009:
 - ◆ Old: ST122, ST136, ST145, ST177
 - ◆ New: T5165, T5166, T5167, T5168
- Tx0 replaced on 16 June 2010. Old T5165, new T3100
- Tx failed. Tx1: T5166 replaced by T3242 on 28 July 2010
- Tx3 replaced on 23 August 2010: Old: T5168, New: ST143
- Tx2 replaced on 23 November 2010. Old T5167, New ST061
- Tx2 replaced on 1 March 2011. Old ST061, new T6138
- Tx0, Tx1, Tx3 replaced on 27 September 2011:
 - ◆ Old: T3100, T3242, ST143
 - ◆ New: T6342, T6343, T6344
- Tx2 replaced on 29 February 2012. Old T6138, New T6739

-- JohnHill - 06-Mar-2012

This topic: Main > AtlasSctBoc_097

Topic revision: r10 - 2012-03-06 - JohnHill



Copyright © 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback