

- Sent to CERN on 1 March 2006.
- Firmware 006/clock hardware fix done.
- Final QA done on 18 May 2006.
- Installed in USA15 on 5 June 2006.
- Tx plugins replaced on 28 July 2009:
  - ◆ Old: ST405, ST224, ST407, ST408
  - ◆ New: T5597, T5598, T5600, T5601
- Tx0 replaced on 25 November 2010. Old T5597, New ST161
- Tx1 and TX3 replaced on 10 May 2011. Old T5598,T5601. New ST503,ST995
- All 4 Tx plugins replaced on 26 August 2011:
  - ◆ Old: ST161, ST503, T5600, ST995
  - ◆ New: T6391, T6393, T6394, T6395
- Rx plugins changed in July 2013 (0-7): x x SR893 SR894 SR895 SR896 SR897 SR898

-- JohnHill - 23-Aug-2013

---

This topic: Main > AtlasSctBoc\_113

Topic revision: r6 - 2013-08-23 - JohnHill



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

or Ideas, requests, problems regarding TWiki? use Discourse or Send feedback