

- Sent to CERN on 8 May 2006.
- Firmware 006/clock hardware fix done.
- Final QA done on 17 May 2006.
- Installed in USA15 on 17 August 2006.
- Tx plugins replaced on 28 July 2009:
 - ◆ Old: ST463, ST464, ST465, ST466
 - ◆ New: T5382, T5383, T5385, T5386
- Tx0 replaced on 4 October 2010. Old T5382, New T3129
- Tx1 and Tx2 replaced on 1 March 2011. Old T5383 and T5385, New T6092 and T6088
- Tx3 replaced on 1 August 2011. Old T5386, New ST395
- All 4 Tx plugins replaced on 19 January 2012:
 - ◆ Old: T3129, T6092, T6088, ST395
 - ◆ New: T6630, T6631, T6632, T6633
- HOLA replaced by dual -port version for FTK on 19 January 2012
- Rx plugins changed in July 2013 (0-7): SR553 SR554 x x SR557 SR558 SR559 SR560

-- JohnHill - 21-Aug-2013

This topic: Main > AtlasSctBoc_128

Topic revision: r7 - 2013-08-21 - JohnHill



Copyright &© 2008-2020 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback