

-- AndreasKorn - 15 Jan 2007

- arrived at CERN 12 Jan 2007, not fully tested yet
  - installed in USA15
  - no configuration through TXC, not a ROD problem (swapped ROD's)
- 

This topic: Main > AtlasSiliconROD\_194

Topic revision: r2 - 2008-03-31 - AndreasKorn



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback