

-- AndreasKorn - 15 Jan 2007

- arrived at CERN 12 Jan 2007, not fully tested yet
 - installed in USA15
 - no configuration through TXC, not a ROD problem (swapped ROD's)
-

This topic: Main > AtlasSiliconROD_194

Topic revision: r2 - 2008-03-31 - unknown



Copyright &© 2008-2021 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.
or Ideas, requests, problems regarding TWiki? use [Discourse](#) or [Send feedback](#)