

-- Andreas Korn - 09 Feb 2006

- arrived at CERN 3 Feb 2006, tested with ROD CLK 2 Feb 2006
 - installed 2nd crate in SR1 2 Aug 2006
 - problem with sending all L1ID's over SLink marked for repair
 - send back to LBNL for repair 6 Feb 2008
 - Returned to CERN 10.04.2014
-

This topic: Main > AtlasSiliconRod_206

Topic revision: r5 - 2014-04-10 - DaveRobinson



Copyright © 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback