

-- Andreas Korn - 09 Feb 2006

- arrived at CERN 2 Feb 2006, tested with ROD CLK 2 Feb 2006
 - installed in SR1 5 Apr 2006
 - installed in USA15
 - occurrence of dead MDSP possibly bad configuration, fixed by reset
-

This topic: Main > AtlasSiliconRod_207

Topic revision: r3 - 2008-03-31 - Andreas Korn



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback