

-- Production Nodes Status - Yvan Calas Wiki Homepage

gdrb05 : RB for xxxx (Mirrored Disks)

- 2005-08-10: a devis has been requested for the hdg disk (cf. mail written by Tim Whibley). [gdrb05 still with the broken status.](#)
- 2005-08-03: [hda changed](#). Helge Meinhard contacted by Alexander Ferrer today in order to create a devis for this machine. [gdrb05 still with the broken status.](#)
- 2005-07-25: [hda + hdg \(RAID disk\) failures](#). Machine blocked but I succeeded to restart it. [Status changed to broken.](#)
- 2005-07-19: machine renamed to gdrb05. SL 3.0.5 + Raid software + RB + fabric monitoring installed, stress test using iozone succeeded. [This node moves to the production cluster.](#)
- 2005-07-14: machine renamed to lxb1469.
- 2005-07-01: machine tbed0034 given by Bernd Panzer-Steindel.

This topic: Main > YvanCalasGDProductionNodesStatusGDRB05

Topic revision: r6 - 2005-08-15 - YvanCalas



Copyright &© 2008-2019 by the contributing authors. All material on this collaboration platform is the property of the contributing authors.

Ideas, requests, problems regarding TWiki? Send feedback