


ATLAS HGTD Preliminary



Typical Single Event Burnout mark is shown in the right plot (2019 DESY test-beam with 5 GeV e). The reconstructed track in the SEB event pointed to the location of the burn mark (middle and right plot). All the reconstructed tracks distribution across the detector before SEB is shown in the left plot.